

9000xDrive Software Release Notes

9000xDrive_2.0.38.exe

released: June 2018

- Fixed display of subfolders on option cards
- Fixed Can-bus connection issues
- Fixed cybersecurity vulnerabilities.

9000xDrive_2.0.26.exe

released: June 2016

- Windows 10 operating system supported
- OPTE9 option card description file updated
- Fixed problem which caused signal binary value dialog not to open in datalogger view.
- Improved signal name search logic for signals without names in datalogger file.
- Fixed problems while opening trend record (.tlf) files from external media.
- SVX2 related datalogger problem fixed.

9000xDrive_2.0.20.exe

released: April 2015

- Added support for digital input signals F.1 - F.10.
- Added support for IXXAT Usb to CAN V2 compact.
- Fixed bug which caused overflow error to stop application generation in case of certain applications.
- Fixed bug which prevented using UDINT type variable as datalogger trigger



Powering Business Worldwide

Additional Help

In the event additional help is needed:

In the US or Canada: please contact the Technical Resource Center at 1-877-ETN-CARE or 1-877-326-2273.

Location	Contact
United States	Technical Resource Center at 1-877-ETN-CARE or 1-877-326-2273.
Canada	
Europe	

All other supporting documentation is located on the Eaton web site at www.eaton.com