

PDG1 Screw Terminal / End Cap Kit, 125 amps, 4 poles



Cat. No - PDG1X4TS125

Style No - 66A1592G38

Quantity - 1 Kit

Package content:

- 1 End Cap
- 4 Torque Screws
- 4 Lock Washers
- 4 Flat Washers
- 4 Nuts



786689164973

- Disconnect voltage and trip breaker.
- To install, place nuts flat side into End Cap, as shown, and slide onto breaker base.
- Mount breaker to panel.
- Place wire terminations on top of Breaker Terminals.
- Insert Terminal Screws through washers in order shown, and torque screws to 34 - 38 Lbs-In (4.0-4.4 N-m).

PDG1 Screw Terminal / End Cap Kit, 125 amps, 4 poles


Cat. No - PDG1X4TS125

Style No - 66A1592G38

Quantity - 1 Kit

Package content:

- 1 End Cap
- 4 Torque Screws
- 4 Lock Washers
- 4 Flat Washers
- 4 Nuts



786689164973

- Disconnect voltage and trip breaker.
- To install, place nuts flat side into End Cap, as shown, and slide onto breaker base.
- Mount breaker to panel.
- Place wire terminations on top of Breaker Terminals.
- Insert Terminal Screws through washers in order shown, and torque screws to 34 - 38 Lbs-In (4.0-4.4 N-m).



PDG1 Screw Terminal / End Cap Kit, 125 amps, 4 poles



Cat. No - PDG1X4TS125

Style No - 66A1592G38

Quantity - 1 Kit

Package content:

- 1 End Cap
- 4 Torque Screws
- 4 Lock Washers
- 4 Flat Washers
- 4 Nuts



786689164973

- Disconnect voltage and trip breaker.
- To install, place nuts flat side into End Cap, as shown, and slide onto breaker base.
- Mount breaker to panel.
- Place wire terminations on top of Breaker Terminals.
- Insert Terminal Screws through washers in order shown, and torque screws to 34 - 38 Lbs-In (4.0-4.4 N-m).

PDG1 Screw Terminal / End Cap Kit, 125 amps, 4 poles


Cat. No - PDG1X4TS125

Style No - 66A1592G38

Quantity - 1 Kit

Package content:

- 1 End Cap
- 4 Torque Screws
- 4 Lock Washers
- 4 Flat Washers
- 4 Nuts



786689164973

- Disconnect voltage and trip breaker.
- To install, place nuts flat side into End Cap, as shown, and slide onto breaker base.
- Mount breaker to panel.
- Place wire terminations on top of Breaker Terminals.
- Insert Terminal Screws through washers in order shown, and torque screws to 34 - 38 Lbs-In (4.0-4.4 N-m).