



Powering Business Worldwide

EATON INDUSTRIAL CORPORATION CUSTOMER SERVICES TECHNICAL PUBLICATIONS INDEX

REVISION: July 1, 2010

| <u>PART NUMBER</u> | <u>DESCRIPTION</u> | <u>APPLICABLE A/C MODEL</u> | <u>ATA #</u> | <u>REV NO. DATED</u> | <u>SERV BULL SERV LTRS</u> | <u>SERV BULL SERV LTRS</u> |
|--------------------|---|---------------------------------|-----------------------------------|--------------------------|----------------------------------|--------------------------------|
| 40574 (3715) | ACTUATOR | B727/B737 | 28-20-01 | 8-11/25/03 | SB61163-28-09 | SB3715-20-05 |
| 40574-2 (3715-7) | ACTUATOR | B727 | 28-20-01 | 8-11/25/03 | SB61163-28-09 SB138 | SB3715-20-05 |
| 40574-4(EM487-4) | ACTUATOR DC | B727/B737 | 28-20-33 | 1-10/01/97 | SB40574-28-01 SB61163-28-01 | SB61163-28-08 SB61163-28-09 |
| 40575 (3360) | ACTUATOR | B727 | 28-20-03 | 7-06/25/02 | SB3360-20-01 | SB12.1.3360 |
| 40665(3715-1) | ACTUATOR | B737 | NONE | 07/01/77 | | |
| 40884-4,-44,-6 | VALVE UNIT | B747/B757/B767 | *28-20-31 | 1-02/15/00 | SB60160-28-4 | |
| 40884-7 | VALVE UNIT | B757/B777 | *28-20-29 | 09/01/94 | | |
| 40884-8 | VALVE ASSY | B777 | *28-20-37 | 03/01/02 | | |
| 40884 (ALL) | ACTUATOR | B737/B747/B757/ B767 | *28-23-53 | 01/15/2007 | | |
| 40885-1 | SEE 60160 SERIES | B747/757/767 | 28-20-05 | 8-05/15/93 | | |
| 40885-2,-22,-4,-10 | CONTROL UNIT | B747/B757/B767 /B777 | 28-20-32 | 2-09/23/03 | SB60160-28-4 | SB40885-28-01 |
| 40885-5,7 | CONTROL UNIT | B757/B777 | 28-20-30 | 1-4/01/99 | SB40885-2-28-01 SB40885-28-02 | |
| 40885-8 | CONTROL UNIT | B777 | 28-20-36 | 03/01/02 | | |
| 40885-24 | CONTROL UNIT | B767-400 | 28-20-34 | 1/20/00 | | |
| 4982 | MOTOR ASSEMBLY | CONV 580 | -- | B-08/29/89 | | |
| 60007-1 | REFUEL OVERPRESS REG | DC9/MD80 | 28-20-22 | 10/15/91 | | |
| 60051 | SEE 61183, 61185 MANUAL | | | | | |
| 60102 | FUEL SCAVENGE EJECTOR | DC10/L1011 | 28-20-08 | 06/01/71 | | |
| 60127 & 6568 | MANUAL FUEL SHUTOFF VLV | B727/B737 | 28-20-3 | 09/22/67 | SB162, SB162A | |
| 60128 | SEE 61183, 61185 MANUAL | | | | | |
| 60160-SERIES | PRESS FUEL SHUTOFF VLV | B747/B757/B767 | 28-20-05 | 8-05/15/93 | SIL60160-28-1 SB60160-28-4 | SIL60160-28-3 SB115 |
| 60160-8 | SEE 40885-5,7 & 40884-7 | B777-200 | | | | |
| 60213-SERIES | PRESS FUEL RECEPT | B747 | **28-20-06 | 3-01/25/74 | SIL60213-28-2 | |
| 60213 (ALL) | PRESS FUEL RECEPT & DEFUELING VALVE ASSEMBLY | B747, B707,B767 | **28-23-68 | 04/20/2008 | | |
| 60273-3,-4 | WATER INJECTION PUMP | B747 | 82-20-03 | 1-10/05/72 | | |
| 60273-6 THRU -9 | WATER INJECTION PUMP | B747 | 82-20-07 | 1-05/01/75 | SB129 | |
| 60281 & -1 | WATER INJECTION CHECK VLV | B747 | 82-20-04 | 1-08/15/72 | SB117 | |
| 60324 | FUEL/WATER SCAVENGE EJECT | DC10/MD11/L1011 | 28-20-07 | 07/01/70 | | |
| 60456 & -1 | WATER INJECTION PUMP | DC10 | 82-20-06 | 1-03/25/74 | | |
| 60490 | FUEL PRESSURE REG ASSY | BEECH | 28-51-05 | 03/15/76 | | |
| 60605 | M.O. FUEL SHUTOFF VALVE | B727 | 28-20-09 | 12/28/73 | SB162 | |
| 60785 | SRGE TNK+-PRESS RLF VLV | B737 | NONE | 10/01/76 | | |
| 61162 | FUEL SHUTOFF VALVE | B737 | 28-20-17 | 1-10/15/95 | SB162A | |
| 61163 | FUEL SHUTOFF VALVE | B737 | 28-20-18 | 3-01/30/07 | SB138, SB162A | SB61163-28-01 |
| | | | | | SB61163-28-02/03 | SIL61163-28-04 |
| | | | | | SIL61163-28-05 | SRL61163-28-06 |
| | | | | | SB61163-28-07 | SB61163-28-08 |
| | | | | | SB61163-28-09 | SB40574-28-01 |
| 61183, 61185 | FUEL SHUTOFF VALVE | B727/B737 | 28-20-02 | 3-11/1/96 | SB61183-28-02 | SB61185-28-03 |
| | | | | | SB162 | SB61163-28-08 |
| | | | | | SB61163-28-09 | SB40574-28-01 |
| | | | | | SB138 | SB162A |
| 61560-1 | REFUEL VALVE | J-41 | 28-20-23 | 03/15/92 | | |
| 61561 | REFUEL SOLENOID VALVE | J-41 | 28-20-24 | 03/15/92 | | |
| 61562 | REFUEL/DEFUEL COUPLING | J-41 | 28-20-25 | 03/15/92 | | |

**EATON INDUSTRIAL CORPORATION
CUSTOMER SERVICES
TECHNICAL PUBLICATIONS INDEX**



Powering Business Worldwide

REVISION: July 1, 2010

| <u>PART NUMBER</u> | <u>DESCRIPTION</u> | <u>APPLICABLE A/C MODEL</u> | <u>ATA #</u> | <u>REV NO. DATED</u> | <u>SERV BULL SERV LTRS</u> | <u>SERV BULL SERV LTRS</u> |
|--------------------|--|---------------------------------|--------------|--------------------------|--------------------------------|--------------------------------|
| 61563 | DEFUEL VALVE | J-41 | 28-20-26 | 03/15/92 | | |
| 61564 | CHECK VALVE | J-41 | 28-20-27 | 03/15/92 | | |
| 6173 | WATER INJECTION PUMP | B707 | 82-1-1 | 01/31/58 | | |
| 6173-1 | WATER INJECTION PUMP | DC8 | -- | 01/21/72 | | |
| 6187-1 | REGULATOR VALVE | 880/990 | 28-1-1 | 05/05/61 | | |
| 6191-1 TO -8,-13 | FUEL JETTISON PUMP | 880/990 | 28-1-1 | 03/15/62 | | |
| 6211 | WATER CHECK/DRAIN VLV | B707 | 38-1-1 | 12/01/58 | | |
| 6347 | SEE 61871-1 | 880/990 | 28-1-1 | 05/05/61 | | |
| 6523 & -1 | WATER INJECTION PUMP | B707 | 82-1-2 | 1-09/29/65 | SB103, SB108 | |
| 535 & -3 | BOOST PUMP BYPASS CK VLV | B727/B737 | 28-20-4 | 02/07/68 | | |
| 6562 | M.O. FUEL SHUTOFF VALVE | B727 | 28-20-1 | 2-06/27/68 | SB162 | |
| 6563 | SEE 61183, 61185 MANUAL | | | | | |
| 6864 | WATER ALCOHOL INJ PUMP | CONV 580 | -- | A-08/29/89 | | |
| 6867 | SEE 60007-1 | | | | | |
| 6956-2 | WATER METHANOL INJ PUMP | CONV 600 | 82/20/1 | 03/30/67 | | |
| | *CMM 28-23-53 REPLACED CMM 28-20-29, 28-20-31, 28-20-35, 28- 20-37. | | | | | |
| | **CMM28-20-06 REPLACED BY CMM 28-23-68. | | | | | |
| | | | | | | |
| | | | | | | |