



Eaton  
5735 W. Las Positas Blvd #100  
Pleasanton, CA 94588  
www.eaton.com/elx

## Product Change Notice

PCN#: EE-PCN15021

December, 2 2015

### CLASSIFICATION OF CHANGE:

Datasheet reference specification change

### DESCRIPTION OF CHANGE:

Recommended PCB layout dimension update

### REASON FOR CHANGE:

Increase manufacturability for different pick and place systems

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

### PARTS FAMILIES AFFECTED:

HCP0805-R40-R
HCP0805-R68-R
HCP0805-1R0-R
HCP0805-1R5-R
HCP0805-2R2-R

### ISSUED BY:

Paul Wiener, Global Product Manager –Magnetics

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).