

P.O. Box 14460  
St. Louis, MO 63178-4460  
114 Old State Road  
Ellisville, MO 63021  
Phone: (636) 527-3877



**Date: July 29, 2009**  
**To: ABC Fuse Customers**  
**Subject: Manufacturing Location Change for ABC 10A and Below Ratings**

Following up on the last ABC/MDA fuse series manufacturing location change notice published in August, 2008; Cooper Bussmann has completed transitioning the various manufacturing locations for the ABC 10A and below ratings (including all options). The primary manufacturing location is now:

**Dongguan Cooper Electronics Co., Ltd**  
**Xinmin Industrial Estate**  
**Chang'an Town**  
**Dongguan City**  
**Guangdong Province, China, 523879**

Previously, these fuses were produced in either Juarez, MX, or in Taiwan. We will continue to ship this product until all work-in-progress (WIP) and finished goods (FG) inventory is depleted.

Regardless of manufacturing location, all Cooper Bussmann fuses meet the appropriate agency specifications as listed on the data sheets. The updated ABC Data Sheet (# 2000) is available online at [www.cooperbussmann.com/datasheets/elx](http://www.cooperbussmann.com/datasheets/elx) .

Thank you for your business, and your cooperation with this transition.

Michael Guo  
Product Manager  
Electronics Circuit Protection  
Cooper Bussmann