

P.O. Box 14460  
St. Louis, MO 63178-4460  
114 Old State Road  
Ellisville, MO 63021  
Phone: (636) 527-3877



**To:** Radial Fuse and 3216TD Chip™ Fuse Customers

**Subject:** Manufacturing Location Change

Cooper Bussmann is changing its manufacturing location for SR-5, SR-5F, SR-5H, SS-5, SS-5F and 3216TD fuses. During the fourth quarter of 2008, Cooper Bussmann will transition production from our Korea manufacturing location to the following locations:

**SR-5/SR-5F/SR-5H:** Cooper Electronic Technologies (Shanghai) Co., Ltd  
955 Sheng Li Road, HeQing Pudong, Shanghai, China 201201

**SS-5/SS-5F/3216TD:** Dongguan Cooper Electronics Co., Ltd  
Xinmin Industrial Estate, Chang'an Town,  
Dongguan City, Guangdong Province, China, 523879

Full capacity is expected to be online in these two China facilities on or before December 1, 2008.

We will continue shipping Korean-made product until all finished goods inventory is depleted.

These manufacturing location changes will not impact form, fit or function performance. All Cooper Bussmann® fuses, regardless of manufacturing location, meet the agency specifications listed on the data sheets. New agency certifications are available upon request. Data sheets are available online at [www.cooperbussmann.com/datasheets/elx](http://www.cooperbussmann.com/datasheets/elx).

Thank you for your business and your cooperation during this transition.

Steve Dawson  
Senior Product Manager, Circuit Protection