



EATON INDUSTRIAL CORPORATION  
FAA REPAIR STATION # QCSR241K  
TECHNICAL PUBLICATIONS  
REVISION :APR 19 2013

PART NUMBER	DESCRIPTION	APPLICABLE A/C MODEL	ATA#	REVISION NO. RELEASE DATE	S B / SIL/ SRL
40574 (3715)	ACTUATOR	B727/B737	28-20-01	8-11/25/03	SB61163-28-09; SB3715-20-05
40574-2 (3715-7)	ACTUATOR	B727	28-20-01	8-11/25/03	SB61163-28-09; SB3715-20-05; SB138
40574-4(EM487-4)	ACTUATOR (DC)	B727/B737	28-20-33	3- FEB 1/2013	SB40574-28-01; SB61163-28-08 SB61163-28-01 SB61163-28-09
40575 (3360)	ACTUATOR	B727	28-20-03	7- 06/25/02	SB3360-20-01 SB12.1.3360
40665(3715-1)	ACTUATOR	B737	NONE	7/1/77	
40884-1,-3,-4, 6, -44	VALVE UNIT	B747/B757/B767	28-23-53	2-SEP 20/2011	SB60160-28-4
40884-7, -23	VALVE UNIT	B757/B777	28-20-29	1- SEP 16/2011	
40884-8	VALVE UNIT	B777	28-20-37	1- AUG 8/2011	
40885-2, -4, 10, -22	CONTROL UNIT	B747/B757/B767	28-20-32	3-AUG 8/2011	SB60160-28-4; SB40885-28-01
40885-5,-7	CONTROL UNIT	B757/B777	28-20-30	2- SEP 12/2011	SB40885-28-02
40885-8	CONTROL UNIT	B777	28-20-36	1- AUG 5/2011	
40885-24	CONTROL UNIT	B767-400	28-20-34	JAN20/00	
4982	MOTOR ASSEMBLY	CONV 580	NONE	B- 08/29/89	
60007-1	REFUEL OVERPRESS REG	DC9/MD80	28-20-22	10/15/1991	
60051/60128	(SEE 61183/61185)				
60102	FUEL SCAVENGE EJECTOR	DC10/L1011	28-20-08	6/1/1971	

**PRINTED COPY IS UNCONTROLLED; CHECK EATON WEBSITE FOR LATEST REVISION:**

<http://www.eaton.com/Eaton/ProductsServices/ProductsbyCategory/Aerospace/CustomerServices/IndexofCMMsandServiceBulletins/index.htm>



EATON INDUSTRIAL CORPORATION  
 FAA REPAIR STATION # QCSR241K  
 TECHNICAL PUBLICATIONS  
 REVISION :APR 19 2013

60127/ 6568	MANUAL FUEL SHUTOFF VLV	B727/B737	28-20-3	9/22/1967	SB162, SB162A
PART NUMBER	DESCRIPTION	APPLICABLE A/C MODEL	ATA#	REVISION NO- DATE	S B / SIL/ SRL
60160-SERIES	PRESS FUEL SHUTOFF VLV	B747/B757/B767	28-20-05	9- SEP 28/2011	SIL60160-28-1 SIL60160-28-3 SB60160-28-4 SB115
60160-8	*SEE 40885-5, -7 & 40884-7	B777-200	*		
60213- SERIES	PRESS FUEL RECEPT & DEFUELING VALVE ASSEMBLY	B747/B707/B767	28-23-68	1- SEP 12/2011	SIL60213-28-2
60273-3,-4	WATER INJECTION PUMP	B747	82-20-03	1- 10/05/72	
60273-6 THRU -9	WATER INJECTION PUMP	B747	82-20-07	1-05/01/75	SB129
60281, -1	WATER INJECTION CHECK VALVE	B747	82-20-04	1-08/15/72	SB117
60324	FUEL/ WATER SCAVENGE EJECT	DC10/MD11/ L1011	28-20-07	7/1/1970	
60456, -1	WATER INJECTION PUMP	DC10	82-20-06	1- 03/25/74	
60490	FUEL PRESSURE REG ASSEMBLY	BEECH	28-51-05	3/15/1976	
60605	M.O. FUEL SHUTOFF VALVE	B727	28-20-09	12/28/1973	SB162
60785	SURGE TANK/ PRESSURE RELIEF VALVE	B737	NONE	10/1/1976	
61162	FUEL SHUTOFF VALVE	B737	28-20-17	1- 10/15/95	SB162A

**PRINTED COPY IS UNCONTROLLED; CHECK EATON WEBSITE FOR LATEST REVISION:**

<http://www.eaton.com/Eaton/ProductsServices/ProductsbyCategory/Aerospace/CustomerServices/IndexofCMMsandServiceBulletins/index.htm>



EATON INDUSTRIAL CORPORATION  
FAA REPAIR STATION # QCSR241K  
TECHNICAL PUBLICATIONS  
REVISION :APR 19 2013

PART NUMBER	DESCRIPTION	APPLICABLE A/C MODEL	ATA#	REVISION NO- DATE	S B / SIL/ SRL
61163	FUEL SHUTOFF VALVE	B737	28-20-18	5- APR 12/2013	SB138, SB162A, SB61163-28-01, SB61163-28- 02/03, SIL61163-28-04, SIL61163-28-05, SRL61163-28-06, SB61163-28-07, SB61163-28-08, SB61163-28-08, SB40574-28-01 SB61163-28-02: REV.1
61183, 61185	FUEL SHUTOFF VALVE	B727/B737	28-20-02	3- 11/1/96	SB61183-28-02, SB61183-28-03, SB162, SB61163- 28-08, SB61163-28- 09, SB40574- 28-01, SB138, SB162A
61560-1	REFUEL VALVE	J-41	28-20-23	3/15/92	
61561	REFUEL SOLENOID VALVE	J-41	28-20-24	3/15/92	
61562	REFUEL/ DEFUEL COUPLING	J-41	28-20-25	3/15/92	
61563	DEFUEL VALVE	J-41	28-20-26	3/15/92	
61564	CHECK VALVE	J-41	28-20-27	3/15/92	

**PRINTED COPY IS UNCONTROLLED; CHECK EATON WEBSITE FOR LATEST REVISION:**

<http://www.eaton.com/Eaton/ProductsServices/ProductsbyCategory/Aerospace/CustomersServices/IndexofCMMsandServiceBulletins/index.htm>



EATON INDUSTRIAL CORPORATION  
 FAA REPAIR STATION # QCSR241K  
 TECHNICAL PUBLICATIONS  
 REVISION :APR 19 2013

6173	WATER INJECTION PUMP	B707	82-1-1	1/31/58	
<b>PART NUMBER</b>	<b>DESCRIPTION</b>	<b>APPLICABLE A/C MODEL</b>	<b>ATA#</b>	<b>REV NO- DATE</b>	<b>SB / SIL/ SRL</b>
6173-1	WATER INJECTION PUMP	DC8	NONE	1/21/72	
6187-1	REGULATOR VALVE	880/990	28-1-1	5/5/61	
6191-1THRU-8,-13	FUEL JETTISON PUMP	880/990	28-1-1	3/15/62	
6211	WATER CHECK/ DRAIN VALVE	B707	38-1-1	12/1/58	
6347	(SEE 61871-1)				
6523, -1	WATER INJECTION PUMP	B707	82-1-2	1- 09/29/65	SB103, SB108
6535, -3	BOOST PUMP BYPASS CHECK VALVE	B727/B737	28-20-4	2/7/68	
6562	M.O. FUEL SHUTOFF VALVE	B727	28-20-1	2- 06/27/68	SB162
6563	(SEE 60128, 61183/ 61185)				
6864	WATER ALCOHOL INJECTOR PUMP	CONV 580	NONE	A- 08/29/89	
6867	(SEE 60007-1)				
6956-2	WATER METHANOL INJECTOR PUMP	CONV 600	82/20/01	3/30/1967	

**PRINTED COPY IS UNCONTROLLED; CHECK EATON WEBSITE FOR LATEST REVISION:**

<http://www.eaton.com/Eaton/ProductsServices/ProductsbyCategory/Aerospace/Customerservices/IndexofCMMsandServiceBulletins/index.htm>