

Release Notes: HFX Service Tool

Version 1.2

HFX Service Tool V1.2.0 is a new release package of the HFX Service Tool. This allows the user to install the Service Tool without requiring Pro-FX Control® or the full HFX Support Package

Installation

Run the installer (SetupHFXServiceTool.exe) and accept all prompts during the installation process. Admin access is required to install this program.

Known Issues

- ETN00025863: Uninstalling the HFX Service Tool removes the launcher, even if it is still needed by Pro-FX Control or Pro-FX Configure.
- ETN00025864: Installing over Pro-FX Configure will sometimes give a nuisance warning that 'launcher.ini' is read-only. Hit 'Retry' to continue the installation.

Contact Information:

Eaton
Hydraulics Group USA
14615 Lone Oak Road
Eden Prairie, Minnesota 55344

Tel. 888 258 0222
952 937 9800
Fax 952 294 7941
Email EatonProFx@eaton.com
Web www.eaton.com



Powering Business Worldwide

Information in this document, including website addresses (URLs) and other Internet references, is subject to change without notice and is provided for informational purposes only. Complying with all applicable copyright laws is the responsibility of the user of this software. Without limiting the rights under copyright, no part of this document may be reproduced, stored in, or introduced into a retrieval system, or transmitted in any form or by any means (electronic, mechanical, photocopying, recording, or otherwise), or for any purpose, without the express written permission of Eaton. Eaton might have patents, patent applications, trademarks, copyrights, or other intellectual property rights covering subject matter in this document. Except as expressly provided in any written license agreement from Eaton, the furnishing of this document does not give a user or reader any license to these patents, trademarks, copyrights, or other intellectual property.

©2015 Eaton. All rights reserved.