

End-of-Life Announcement

EOL Product FX31000 FerrUPS

EOL Date Nov. 14, 2022

EOL Owner Jose L. Medina

JoseMedina3@eaton.com

Eaton is announcing that the FX3100 will be transitioned to End-of-Life status on November 21, 2022. The closest functional replacement to the FX3100 UPS are the Eaton 9SX and 9PX UPSs. EOL units will be available on a first come, first serve basis until inventory is depleted. Eaton acknowledges this difficult decision, and we are dedicated to assisting in whatever way possible during this transition.

For further questions, please contact your Eaton presales team at: CPDIsalesengineering@eaton.com

Part Numbers to be End-of-Life

| Catalog Number | Style Number | Description | Two Suggested Replacement Option Product Lines |
|--|--|--|--|
| FX310000AAA1 FXEBM01 FXEBM03 FXEBM04 FXEBM06 BPEFXMBB02 BPEFMBBM02 | 13505437 FXEBM01 FXEBM03 FXEBM04 FXEBM06 P-103003764 N/A | 3.1kW Ferro Resonant UPS Ferrups FX 48VDC EBM Ferrups FX 48VDC EBM Ferrups FX 48VDC EBM Ferrups FX 48VDC EBM Make Before Break Maintenance Bypass Panel Break Before Make Maintenance Bypass Panel | 9PX Online UPS 700-11,000 VA With Extended Runtime Eaton Or Double conversion UPS Network UPS 9SX Eaton Please consult with Eaton presales team for specific replacement model preference at: CDPIsalesengineering@eaton.com |