

Date: August 3, 2018
To: Bussmann series CCPB Class CF (CUBEFuse™) customers
Subject: End-of-life notice

Dear valued customer:

With the launch of the Bussmann™ series next generation Class CF fuse Compact Circuit Protector Base (cat. no. CCP2B-CF) UL® 98 disconnect switches, the previous iteration of these products are immediately discontinued.

The next generation CCP2B-CF is a direct, drop in replacement with the same form, fit and function.

The legacy products (CCPB-CF) will continue to be available for purchase while inventory lasts. All existing stock is saleable product and should not be returned. The affected catalog numbers, UPCs and recommended direct replacements are listed on the next page.

Should you need technical assistance regarding the next generation CCP2B-CF switches, please contact our Application Engineering team at 1-855-278-7626, or email FuseTech@Eaton.com.

If you have any questions regarding this end-of-life notice, please contact your local Bussmann series product sales representative.

Best Regards,



Eric Treffeisen
Product Manager
ericmtreffeisen@eaton.com

| Amp Rating | Legacy CCPB-CF | | Next generation CCP2B-CF | |
|------------|----------------|--------------|--------------------------|--------------|
| | Catalog Number | UPC | Catalog Number | UPC |
| 15A | CCPB-1-15CF | 051712204897 | CCP2B-1-15CF | 051712790330 |
| | CCPB-2-15CF | 051712204903 | CCP2B-2-15CF | 051712709347 |
| | CCPB-3-15CF | 051712204910 | CCP2B-3-15CF | 051712709354 |
| 20A | CCPB-1-20CF | 051712204927 | CCP2B-1-20CF | 051712709361 |
| | CCPB-2-20CF | 051712204934 | CCP2B-2-20CF | 051712709378 |
| | CCPB-3-20CF | 051712204941 | CCP2B-3-20CF | 051712709385 |
| 30A | CCPB-1-30CF | 051712201520 | CCP2B-1-30CF | 051712709392 |
| | CCPB-2-30CF | 051712201537 | CCP2B-2-30CF | 051712709408 |
| | CCPB-3-30CF | 051712201544 | CCP2B-3-30CF | 051712709415 |
| 40A | CCPB-1-40CF | 051712204958 | CCP2B-1-40CF | 051712709422 |
| | CCPB-2-40CF | 051712204965 | CCP2B-2-40CF | 051712709439 |
| | CCPB-3-40CF | 051712204972 | CCP2B-3-40CF | 051712709446 |
| 50A | CCPB-1-50CF | 051712204989 | CCP2B-1-50CF | 051712709453 |
| | CCPB-2-50CF | 051712204996 | CCP2B-2-50CF | 051712709460 |
| | CCPB-3-50CF | 051712205009 | CCP2B-3-50CF | 051712709477 |
| 60A | CCPB-1-60CF | 051712201551 | CCP2B-1-60CF | 051712709484 |
| | CCPB-2-60CF | 051712201568 | CCP2B-2-60CF | 051712709491 |
| | CCPB-3-60CF | 051712201575 | CCP2B-3-60CF | 051712709507 |
| 70A | CCPB-1-70CF | 051712268059 | CCP2B-1-70CF | 051712709514 |
| | CCPB-2-70CF | 051712268080 | CCP2B-2-70CF | 051712709521 |
| | CCPB-3-70CF | 051712268110 | CCP2B-3-70CF | 051712709538 |
| 90A | CCPB-1-90CF | 051712268066 | CCP2B-1-90CF | 051712709545 |
| | CCPB-2-90CF | 051712268097 | CCP2B-2-90CF | 051712709552 |
| | CCPB-3-90CF | 051712268127 | CCP2B-3-90CF | 051712709569 |
| 100A | CCPB-1-100CF | 051712268042 | CCP2B-1-100CF | 051712709576 |
| | CCPB-2-100CF | 051712268073 | CCP2B-2-100CF | 051712709583 |
| | CCPB-3-100CF | 051712268103 | CCP2B-3-100CF | 051712709590 |