

P.O. Box 14460
St. Louis, MO 63178-4460
114 Old State Road
Ellisville, MO 63021
Phone: (636) 527-3877



September 23, 2005
To: MDX Fuse Customer
Subject: **MDX Fuse END of LIFE NOTICE**

Due to the low MDX fuse market demand, manufacturing site consolidations and the evolution of the equivalent MDL Series, the Cooper Bussmann MDX ¼" ferrule fuse Series is at its end of life as a product offering.

The MDL ¼" time-delay glass fuse Series has voltage ratings that meet those of the MDX and is the recommended replacement. The MDL Series data sheet is on our website (www.cooperbussmann.com).