

## Product Change Notice

July 21, 2014

### CLASSIFICATION OF CHANGE:

Part marking and color change.

### DESCRIPTION OF CHANGE:



Before: Black with white mark



After: Grey with black mark

### REASON FOR CHANGE:

Standardize marking, marking orientation, color, and improve legibility across all HCM Series products.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, PERFORMANCE:

Quality, reliability, and performance are not affected. There are no changes to form, fit, and function of the devices.

### PARTS NUMBERS/SERIES/FAMILIES AFFECTED:

HCM0503-1R0-R	HCM0703-1R5-R	HCM1103-R36-R	HCM1305-R22-R
	HCM0703-2R2-R	HCM1103-R47-R	HCM1305-R47-R
HCM0703-R15-R	HCM0703-3R3-R		HCM1305-R56-R
HCM0703-R22-R	HCM0703-4R7-R	HCM1104-R20-R	HCM1305-R68-R
HCM0703-R47-R	HCM0703-6R8-R	HCM1104-R36-R	HCM1305-R82-R
HCM0703-R68-R	HCM0703-8R2-R	HCM1104-R45-R	HCM1305-1R0-R
HCM0703-R82-R	HCM0703-100-R	HCM1104-R56-R	HCM1305-1R5-R
HCM0703-1R0-R		HCM1104-R90-R	HCM1305-2R2-R

### TIME SCHEDULE:

Start Shipment Date: July 28, 2014. Existing inventory is saleable and should not be returned.

Last Time Buy Date: n/a

Last Time Shipment Date: n/a

### SAMPLE AVAILABILITY:

Available upon request

### QUALIFICATION DATA:

Available upon request

### ISSUED BY:

Paul Wiener, Global Product Manager - Magnetics

If you have any question about this product change, please contact your local Eaton representative.