

P.O. Box 14460  
St. Louis, MO 63178-4460  
114 Old State Road  
Ellisville, MO 63021  
Phone: (636) 527-3877



To: **1/4" Fuse Customers**  
Date: **August 11, 2008**  
Subject: **Manufacturing Location Change for MDA (1/4A to 30A)  
and ABC (12A-30A)**

Cooper Bussmann has completed transitioning the manufacturing locations for the MDA ¼ to 30A and ABC 12 to 30A fuses (including all options). The primary manufacturing location is now:

**Dongguan Cooper Electronics Co., Ltd**  
**Xinmin Industrial Estate**  
**Chang'an Town**  
**Dongguan City**  
**Guangdong Province, China, 523879**

Previously, these fuses were produced in either Juarez, MX, or in Taiwan. We will continue to ship this product until all work-in-progress (WIP) and finished goods (FG) inventory is depleted.

Cooper Bussmann already produces the majority of its 5mm ferrule fuses at this facility, making it an excellent fit for manufacturing the ¼" ferrule fuse.

We will continue to transition the manufacturing of the remaining MDA and ABC part numbers to Dongguan, and will issue similar notification upon completion.

All Cooper Bussmann® fuses, regardless of manufacturing location, meet the appropriate agency specifications as listed on the data sheets. Data sheets are available online at [www.cooperbussmann.com/datasheets/elx](http://www.cooperbussmann.com/datasheets/elx).

Thank you for your business, and your cooperation with this transition.

Steve Dawson  
Senior Product Manager, Circuit Protection